

Hooper

<i>Filename of original image</i>	<i>Page</i>
Hooper 34.tif	2
Hooper 12.tif	3
Hooper 16.tif	4
Hooper 30.tif	5
Hooper 46.tif	6
Hooper 13.tif	7
Hooper 15.tif	8
Hooper 17-19.tif	9
Hooper 23.tif	10
Hooper 27.tif	11
Hooper 29.tif	12
Hooper 35.tif	13
Hooper 39.tif	14
Hooper 45.tif	15

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 34 HOOPERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION ~~c. 1880's~~ 1875' or earlierBUILDING MATERIAL brick veneer siding over stucco-frameSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 12 HOOPERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1923-25BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 16 flooperARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1875BUILDING MATERIAL recent siding over (stucco? or frame?)SIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 30 HOOPERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1925-26BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 46 HOOPERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1923-26BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 13 HOOPERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1885-95BUILDING MATERIAL recent siding over stucco-frameSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 15 HOOPERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION uncertain, probably 1875-~~95~~BUILDING MATERIAL recent siding over stucco-frameSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 17-19 HooperARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit dwellingDATE OF CONSTRUCTION c.1900-1912BUILDING MATERIAL pressed red brick, stone lintels and sillsSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 23 HOOPERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 27 HooperARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c. 1880-~~1890~~BUILDING MATERIAL recent siding over frame - stuccoSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 29 HOOPERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1890BUILDING MATERIAL recent siding over stucco-frameSIGNIFICANCE none

PHOTO DATE: 2-1-71

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 35 HOOPERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1923-26BUILDING MATERIAL imitation brick sidingSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 39 HOOPERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION ~~xx1900~~ c.1890-1900BUILDING MATERIAL recent siding over stucco-frameSIGNIFICANCE none

PHOTO DATE: 20-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 45 HOOPERARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c. ~~1918~~ 1870-75BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 20-1-75