

Jackson

<i>Filename of original image</i>	<i>Page</i>
Jackson 11.tif	2
Jackson 23.tif	3
Jackson 29.tif	4
Jackson 39.tif	5

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 11 Jackson street Cor GrangeARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880 or earlierBUILDING MATERIAL painted two color brickSIGNIFICANCE Priority #5. Age, character.

PHOTO DATE: 5-12-73

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 23 Jackson StreetARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880BUILDING MATERIAL yellow brickSIGNIFICANCE Priority #5. Unusual design.

PHOTO DATE: 21-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 29 Jackson streetARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880 (second floor may be later)BUILDING MATERIAL *INSUL-BRICK SIDING*SIGNIFICANCE Priority #5. Interesting woodwork on verandah

PHOTO DATE: 21-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 39 Jackson street, corner PalmerARCHITECTCONTRACTOR RibbrookORIGINAL OWNER E. BrookingORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1875BUILDING MATERIAL frame, later covered with composition sidingSIGNIFICANCE Priority #5, could be improved with sympathetic restoration. Age, character.

PHOTO DATE: 21-1-75