

Martin

<i>Filename of original image</i>	<i>Page</i>
Martin 1.tif	2
Martin 21-23-25-27.tif	3
Martin 31.tif	4
Martin 59.tif	5
Martin 61.tif	6
Martin 63-65.tif	7
Martin 60.tif	8
Martin 66.tif	9

ARCHITECTURAL INVENTORY

Block No.
Item.

Page

LOCATION 1 Martin Ave sw corner Water Street

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE single family dwelling

DATE OF CONSTRUCTION c. ~~1885-1895~~ 1875

SIGNIFICANCE none

Building Material - painted textured ~~concrete~~ block stucco



PHOTO DATE 20.6.74

ARCHITECTURAL INVENTORY

Block No.
Item.

Page

LOCATION 27-25-23-21 Martin Avenue Terrace

ARCHITECT

CONTRACTOR

ORIGINAL OWNER

ORIGINAL USE four unit dwelling terrace

DATE OF CONSTRUCTION 1875-1885

SIGNIFICANCE limited

BUILDING MATERIAL painted old red brick



PHOTO DATE 28-6-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 31 Martin Avenue, NW corner JamesARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1870-1875 Moved to this location 1920's from James , near Gordon.SIGNIFICANCE Priority #4. Quaint, unique design.BUILDING MATERIAL - stucco, pebble dash.

PHOTO DATE 28-6-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 59 Martin Avenue, SW corner JamesARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1908-1913BUILDING MATERIAL red brick, stone lintels and sills.SIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 61 Martin Avenue, west sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1908-1913BUILDING MATERIAL red brick with stone lintels and sills.SIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 63-65 Martin Avenue, west sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE two unit dwellingDATE OF CONSTRUCTION c.1900-1910BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 60 Martin Avenue, east side,ARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE Brooklyn Sunday SchoolDATE OF CONSTRUCTION c. ¹⁹²³~~1922-26~~ Remodelled c.1960BUILDING MATERIAL tan brickSIGNIFICANCE none

PHOTO DATE: 4-12-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 66 Martin Avenue, east sideARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1905-1913BUILDING MATERIAL red brick with stone lintels and sills.SIGNIFICANCE none

PHOTO DATE: 4-12-74