

Alice

<i>Filename of original image</i>	<i>Page</i>
Alice 6.tif	3
Alice 8.tif	4
Alice 10.tif	5
Alice 12.tif	6
Alice 20.tif	7
Alice 36.tif	8
Alice 38.tif	9
Alice 46.tif	10
Alice 48.tif	11
Alice 50.tif	12
Alice 52.tif	13
Alice 60.tif	14
Alice 64.tif	15
Alice 66.tif	16
Alice 76.tif	17
Alice 80.tif	18
Alice 86-88.tif	19
Alice 92-94.tif	20
Alice - Sacred Heart Church.tif	21
Alice 116-118-120.tif	22
Alice 122.tif	23
Alice 124-128.tif	24
Alice 130.tif	25
Alice 132-134.tif	26
Alice 136.tif	27
Alice 142.tif	28
Alice 150.tif	29
Alice 152.tif	30
Alice 154.tif	31
Alice 156.tif	32
Alice 162.tif	33
Alice 164.tif	34
Alice 166.tif	35
Alice 168.tif	36
Alice 170.tif	37
Alice 174-176.tif	38
Alice 178-180.tif	39
Alice 182.tif	40

Alice 184.tif	41
Alice 200.tif	42
Alice 202-204.tif	43
Alice 206-208.tif	44
Alice 210.tif	45
Alice 212.tif	46
Alice 13-15.tif	47
Alice 19.tif	48
Alice 23.tif	49
Alice 25.tif	50
Alice 29.tif	51
Alice 41-43.tif	52
Alice 45.tif	53
Alice 47.tif	54
Alice 49.tif	55
Alice 63.tif	56
Alice 67.tif	57
Alice 71.tif	58
Alice 73.tif	59
Alice 75.tif	60
Alice 77-79.tif	61
Alice 93.tif	62
Alice 103-105.tif	63
Alice 95-97.tif	64
Alice 107-109.tif	65
Alice, south side, east of Huron - Northern Rubber.tif	66
Alice, south side, east of Huron - former C.P.R Round House.tif	67
Alice 177-187.tif	68

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 6 ALICE STREETARCHITECT UnknownCONTRACTOR —ORIGINAL OWNER —ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1914BUILDING MATERIAL brickSIGNIFICANCE None

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 8 ALICE STREETARCHITECT - unknownCONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION before 1882BUILDING MATERIAL siding over probable stucco or frameSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 10 ALICEARCHITECT unknownCONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1910-1914BUILDING MATERIAL pressed red brickSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 12 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1910-1918BUILDING MATERIAL pressed red brickSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 20 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880SIGNIFICANCE none

Building Material - pressed red brick, cottage



PHOTO DATE 29-11-74

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 36 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1890's - some uncertainty due to changes in street numbering.SIGNIFICANCE - none

Building Material - frame-siding - insul-brick siding over frame



PHOTO DATE 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 38 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1890's or earlierBUILDING MATERIAL frame siding with some creid valley limestone trimSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 46 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1926-7BUILDING MATERIAL pressed brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 48 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1890'sBUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 50 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1922-27BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 9-1-75-

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION S 2 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION before 1882BUILDING MATERIAL yellow brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 60 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880BUILDING MATERIAL stucco over probably yellow brickSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 64 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE Appears to have been barn or workshop for #66DATE OF CONSTRUCTION c1890'sBUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION CC ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1880'sBUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE:

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 76 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880BUILDING MATERIAL yellow brickSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 80 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1882-84BUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE:

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 86-88 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE two family dwellingDATE OF CONSTRUCTION c.1900BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 92-94 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE two family dwellingDATE OF CONSTRUCTION c.1900BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION SACRED HEART CHURCH (R.C.)ARCHITECT -CONTRACTOR -ORIGINAL OWNER Hamilton Diocese of Roman Catholic ChurchORIGINAL USE Church edificeDATE OF CONSTRUCTION 1922BUILDING MATERIAL red brick and frameSIGNIFICANCE No architectural Significance
limited Historic significance for the parish

PHOTO DATE:

ARCHITECTURAL INVENTORY

Block No.

Page

Item.

LOCATION 116-118-120

ALICE

ARCHITECT -CONTRACTOR -ORIGINAL OWNER - 116: Ideal GroceryORIGINAL USE 118-120 two residential units
116 store and apartmentDATE OF CONSTRUCTION 118-120: 1923-25
116 1925-26SIGNIFICANCE none

PHOTO DATE 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 122 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1900-1910BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION ⁸
~~124-128 Alice~~ 124-128 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE 124 - single family dwelling
128 - bakeryDATE OF CONSTRUCTION 124: 1900-1910
128: 1923-25BUILDING MATERIAL 124: Red brick
128: now faced with flagstone veneer over red brickSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 130 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1890BUILDING MATERIAL yellow brickSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION ~~132-134~~⁴ 132-134 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE grocery store and dwellingDATE OF CONSTRUCTION c.1900 -1920BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 136 ALICE STREETARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1900-1910BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 142 Alice Street, NW Corner SackvilleARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1919BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 160 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE grocery storeDATE OF CONSTRUCTION c.1900-1912BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 29-1--74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 152 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE uncertainDATE OF CONSTRUCTION 1900-1910BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 154 ALICEARCHITECTCONTRACTORORIGINAL OWNERORIGINAL USE uncertainDATE OF CONSTRUCTION 1900-1910BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 156 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1926-1927BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 162 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE ~~cr900~~ single family dwellingDATE OF CONSTRUCTION c.1900BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 164 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 166 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1900BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 168 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER-ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1900-1910BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 170 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1900-1910BUILDING MATERIAL StuccoSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 174 - 176 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwelling with storeDATE OF CONSTRUCTION 1922-1923, store added 1924BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 178-180 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE two family dwelling unitsDATE OF CONSTRUCTION c.1914-15BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 1F2 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1923-1925BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 184 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE uncertainDATE OF CONSTRUCTION 1923-25BUILDING MATERIAL more recent concrete block in front of frameSIGNIFICANCE none

PHOTO DATE: 3.2.75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 200 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1923-25BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 202
204 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNERORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1923-25 with later addition in frontBUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 206-208 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE two family dwelling unitsDATE OF CONSTRUCTION 1923-25BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-7-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 210 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1923-25BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 212 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER P.B. DurkinORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1925-1926 1°BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE:

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 13-15 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE two family dwelling unitsDATE OF CONSTRUCTION 1914-15BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 19 ALICE STREETARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1880BUILDING MATERIAL stuccoSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 23 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1890BUILDING MATERIAL recent siding over ??SIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 25 ALICE STREETARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1890'sBUILDING MATERIAL red brick (veneered?)SIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 29 ALICEARCHITECT -CONTRACTOR--ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1890BUILDING MATERIAL recently remodelled with new siding and reduced window sizes.SIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 41-43 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE two family dwelling unitsDATE OF CONSTRUCTION about 1928-29BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 45 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1880'sBUILDING MATERIAL synthetic brick veneer of later dateSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 47 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER N. ValnietsORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1923-5'BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 49 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE shopDATE OF CONSTRUCTION probably 1920'sBUILDING MATERIAL brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 63 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1890's -possibly to 1883BUILDING MATERIAL probably stucco under variety of recent sidingsSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 67 ALICE STREETARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1922BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 71 ALICE STREETARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION c.1922BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 73 ALICEARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1923BUILDING MATERIAL red brick and stuccoSIGNIFICANCE none

PHOTO DATE: 2-2-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 75 ALICE STREETARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1919BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 77-79 ALICE STREETARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE two family dwelling unitsDATE OF CONSTRUCTION 1919BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 93 ALICE STREETARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE single family dwellingDATE OF CONSTRUCTION 1914BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-71

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 103-105 ALICE STREETARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE two family dwelling unitsDATE OF CONSTRUCTION c.1900BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 95-97 ALICE STREETARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE two family dwelling unitsDATE OF CONSTRUCTION c.1900BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9.1.75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 107-109 ALICE STREETARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE two family dwelling units, plus later storeDATE OF CONSTRUCTION c.1900, store probably 1920's.BUILDING MATERIAL red brickSIGNIFICANCE none

PHOTO DATE: 9-1-75

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION ALICE STREET south side, east of Huron St.ARCHITECT -CONTRACTOR -ORIGINAL OWNER Northern Rubber CompanyORIGINAL USE factoryDATE OF CONSTRUCTION 1920BUILDING MATERIAL brick and concreteSIGNIFICANCE none

PHOTO DATE: 29-11-74

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATIONFormer C.P.R. Round House, south side Alice Street,
east of Huron Street.ARCHITECT

-

CONTRACTOR

-

ORIGINAL OWNER

Guelph Junction Railway with C.P.R.

ORIGINAL USE

Railway Round House

DATE OF CONSTRUCTION c.1990-1910BUILDING MATERIAL

frame

SIGNIFICANCE

None except for possible interest of Railway buffs.



PHOTO DATE:

ARCHITECTURAL INVENTORYBLOCK No.
ITEM.

PAGE

LOCATION 177-187 Alice StreetARCHITECT -CONTRACTOR -ORIGINAL OWNER -ORIGINAL USE six residence units in terraceDATE OF CONSTRUCTION 1900-1914BUILDING MATERIAL frameSIGNIFICANCE none

PHOTO DATE: 29-11-74